


Managing Dampness, Mould & Condensation

Procedure



Contents

1. Purpose
2. Scope
3. Contributory Factors of Dampness, Mould & Condensation
4. Four Main Categories of Dampness
5. Procedure / Process
6. Turning insight into action
7. Monitoring and Compliance

1. Purpose

- 1.1. To provide a Group wide procedure that will create a consistent approach to addressing cases of mould and condensation or dampness through to resolution and rectification of cause.

2. Scope

- 2.1. The procedure applies to Wheatley Group employees, contractors and stakeholders

3. Contributory Factors of Dampness, Mould & Condensation

3.1. Fuel poverty

It is recognised that fuel poverty is a major factor in cases of condensation which can lead to mould problems when customers are unable to afford to heat their home effectively.

3.2. Cold Bridging

Cold Bridging can be found in many areas including poorly installed cavity wall insulation for example. Where a gap occurs in the insulation this can cause areas to become colder, which would then be at risk of increased condensation.

3.3. Blocked or broken ventilation

This would include blocked soot or air bricks and broken window trickle vents

3.4. Broken or no extractor fans

Where possible, all kitchens, bathrooms and utility rooms should have a functioning extractor fan.

3.5. Radiators

Heating systems performance is not always at the standard required to prevent condensation. Radiators may be undersized for the room volume and can be located on internal walls creating colder external walls.

3.6. Missing/damaged render or pointing on brickwork

There could be various reasons for poor or broken pointing (i.e. the finish between bricks) on parts of a brick wall which may have created cold spots for condensation and penetrating damp. The same can also be true with damaged render systems

3.7. Leaking guttering

Guttering can, over time, corrode, warp or sag causing leaking joints. Lack of effective maintenance can result in blocked or choked gutters and downpipes that can, through time, cause damage to the fabric of the building.

3.8. **Leaking roofs**

This could be caused by many things i.e. damaged or missing tiles, damaged flashing, roof vents or chimneys, blocked gutters or simply that the roof has reached the end of its serviceable life.

3.9. **Unvented and condensing tumble dryers**

These can produce excessive amounts of water vapour in the property, encouraging condensation.

3.10. **Customer management of the home**

Excessive humidity within the home and the lack of adequate ventilation is the primary cause of condensation. Drying clothes on space heaters, cooking with lids off pans, and over-crowding all add to the moisture levels within a property.

3.11. **Rising damp**

Rising damp can occur where there is missing or ineffective damp proof course or where a high ground level breaches the damp proof course.

4. **Four Main Categories of Dampness**

4.1. **Penetrating dampness**

This type of dampness will only be found on external walls or, in the case of roof leaks, on ceilings. It only appears because of a defect in the structure of the home, such as missing pointing to the brickwork, missing roof tiles, loose flashing or leaking gutters. These defects then allow water to pass from the outside to the inner surfaces. Penetrating dampness is far more noticeable following a period of rainfall and will normally appear as a well-defined 'damp-patch' which looks and feels damp to the touch. "Tide marks" will be left, even in periods of dry weather.

4.2. **Defective plumbing**

Leaks from water and waste pipes, especially in bathrooms and kitchens, are relatively common. They can affect both external and internal walls and ceilings. The affected area looks and feels damp to the touch and stays damp whatever the weather conditions outside. An examination of the water and waste pipes in the kitchen and bathroom and the seals around the bath, shower and sinks will usually find the problem. In cases when leaks are not attended to, rot may become established in wooden joists and floor boards leading to a risk of collapse in severe cases.

Mould may be seen with this type of dampness and even fungi are not uncommon if the defects are not addressed.

4.3. **Rising dampness**

This is caused by water rising from the ground into the home. The water gets through or around a defective damp proof course (DPC) or passes through the natural brickwork if the property was built without a DPC. Rising damp will only affect basements and ground floor rooms. It will normally rise no more

than 36 inches above ground level (900mm) and usually leaves a 'tide mark' low down on the wall. You may also notice white salts on the affected areas.

Rising damp will be present all year round but is more noticeable in winter. If left untreated it may cause wall plaster to crumble and paper to lift in the affected area. Mould will rarely be seen where there is rising damp (and then only in the early stages). This is because rising dampness carries with it salts that prevent the growth of mould.

4.4. **Condensation and mould growth**

This is by far the most common enquiry we receive from customers which often leads to a repair request.

Condensation is caused by water vapour or moisture in the air, inside the dwelling, coming into contact with a colder surface, such as a window or wall. The drop in temperature causes water to form on the surface. This water may then soak into the wallpaper, paintwork or plasterwork. Mould spores are invisible to the naked eye but are in the air all around us all of the time and will quickly grow on surfaces where condensation has formed into a visible covering.

Condensation can be more prevalent during the colder months and we often experience a spike in customer demand during Autumn and Winter. A symptom of condensation is mould growth which is usually found in the corners of rooms, north facing walls and on or near windows. It is also found in areas of little air circulation such as behind wardrobes and beds, especially when they are pushed up against external walls. It also forms in bathrooms and kitchens as they are high moisture areas or in properties which are overcrowded.

All homes are affected by condensation at some point however certain activities can increase the problem and good practices can eliminate this from becoming a bigger problem. Condensation and mould growth can often be a consequence of customer habits and lifestyles. Cooking, washing and drying clothes indoors etc. all produce water vapour that can only be seen when tiny drops of water (condensation) appear on colder surfaces such as walls, windows, ceilings or mirrors and often unseen on clothing, shoes and furniture.

The amount of condensation in a home depends upon a number of things, most importantly-

- How much water vapour is produced by the actions of its residents
- How cold or warm the property is
- How much air circulation (ventilation)
- How well the property has been insulated.

Simply turning up the heating will not sort out the problem, this may only temporarily reduce condensation. All factors may need to be looked at to reduce the problem. The first sign of a problem is often water vapour condensing on windows and other cold surfaces, which then takes a long time to disappear. This allows the surfaces to become damp resulting in mould growing on these damp areas.

5. Procedure / Process

How to Manage a Report of Damp or Mould and Condensation

5.1. First contact

- Call received by Customer First Centre
- A service request will be sent to Fuel advisor team for condensation
- Fuel advisor to give tailored advice to alleviate condensation and provide energy savings
- Where there is no evidence of lifestyle related condensation, the Fuel Advisor should request the assistance of a Repairs, Investment & Compliance Officer (RICO) to help conduct a full survey of the property.
- Fuel advisor to leave monitoring/remedial products with the customer, hydrometers, mini dehumidifiers and mould wash down sprays to be left with every customer, consideration also for top up voucher for customers struggling to heat homes
- Where required raise a line for antifungal wash down via Go Mobile
- Fuel advisor to update Astra and feedback to Housing Specialist Team leads
- Housing specialist team to contact customer after 28 day period to assess effectiveness, where issue remains unresolved escalate to Repairs Investment & Compliance Team (bullet 3 below)

5.2. Repeat contact

- Customer calls with follow up or repeat contact. Customer Service Advisor probes if this is a follow up to an ongoing open case or if the case had been closed. Open cases will be referred to the Fuel Advisor with all qualifying information.
- In event the customer wishes to escalate their case or identify that their case was closed in the last 6/12 months, and this has reoccurred or identify that new condensation/mould/dampness issues exist. The case will be qualified by Customer Service Advisor and passed to Housing Specialist Team

- Housing Specialist Team will triage call and collaborate with FA to identify if a follow up visit or a joint visit with a RICO would be more appropriate. Identifying if issues have worsened or if new areas affected and if technical inspection may be required. At this point of escalation a report should be created jointly with RICO and Fuel Advisor to record the assessment and identify actions to resolve.
- The HST will look to resolve any repeat or recurring contacts. The objective to minimize any dissatisfaction, should the customer identify that they are still dissatisfied and look to pursue a complaint this will be recorded and progressed in line with complaints policy.

Fuel advisor to leave monitoring/remedial products with the customer, hydrometers, mini dehumidifiers and mould wash down sprays to be left with every customer, consideration.

5.3. How to Manage a Report of Defective plumbing

- Call received by Customer First Centre
- Customer Service Adviser will assess the repair type following discussion with the customer
- Repair will be categorised as either Emergency (response within 24 hours but typically within 4 hours) where the leak cannot be contained and will likely cause significant damage or as an Appointment (up to 15 days based on customer requirements but typically within 3 days) where the customer confirms for example that there is a minor drip which can be contained
- Most repairs of this type are first time fix, however where a trades operative identifies additional works for example water staining on ceilings below a bathroom, water damage to kitchen fitments, a follow on technical inspection will be arranged to establish any further remedial works.

5.4. How to Manage a Report of Penetrating dampness & Rising dampness

- Call received by Customer First Centre
- Customer Service Adviser will assess the repair type following discussion with the customer
- Repair will be generally be categorised as Programmed and an appointment will be arranged for a technical inspector to visit the property to fully diagnose the issue
- Most repairs of this type are associated with either defective guttering/downpipes and/or missing or dislodged roof tiles

Following the technical inspection remedial works will be completed within 30 days where possible (typically within 14 days). In some instances where the work is more complex or specialist in nature, repair works cannot always be carried out as part of the responsive repairs service as they generally require more planning, resources and non-standard materials. For reasons of efficiency, major repairs and specialist works may be grouped together in a programme of works

6. Turning insight into action

As well as addressing reports of dampness, mould and condensation effectively, taking a proactive approach will also be key to success. Such an approach is made increasingly possible through the insight that can be gained from the extensive repairs and investment history we have for our properties and from the data that can be collected on the environment in homes using sensor technology. Where applicable we will deploy analysis and sensor technology to build understanding and to inform action including campaigns, staff resource deployment and property investment.

7. Monitoring and Review

This Procedure will be reviewed every two years as Standard
This procedure will be reviewed should legislation, Regulations or internal organisational change and amendments are required